



TEST REPORT

98, Gyoyukwon-ro, Gwacheon-si, Gyeonggi-do, 13810, Korea

TEL 82-2-2164-0011

FAX 82-2-2634-1008

Report No : TAK-2019-063258

Representative : In-Tae Kim

Company name : Pinostory

Address : 401ho, 35, Bangbae-ro 42-gil, Seocho-gu, Seoul, Korea.

Receipt Date : 2019.04.16.

Test Completion Date : 2019.04.24.

Sample name : SafeTSYL (SBF006_F)

Test Results

TEST ITEM	UNIT	SAMPLE	RESULT	TEST METHOD
Deodorization : Carbon monoxide (Initial)	ppm	-	52(52)	Client Provided Test Method
Deodorization : Carbon monoxide (After 30 min)	ppm	-	3(52)	Client Provided Test Method

1. Test Condition : Temperature (23 ± 5) °C, Humidity (40 ± 5) % R.H.

2. Test Container : 10 L Tedlar Bag

3. Sample Input : 1 ea

4. Test Instrument : Multi gas analyzer (MK6000, rbr, Germany)

5. () is blank test result

6. Test result value was not corrected by blank test value

- Usage of Report : QUALITY CONTROL

Note : 1. The test results of this test report are only limited in to the samples and sample names provided by the client and do not guarantee the quality of all products of the client. You Can check website (www.ktr.or.kr) or QR code to verify the authenticity of the certificate.

2. This test report shall be used only within the purpose of its defined usage and shall not be used for public relation, advertisement and lawsuit.

3. This test report is only valid when printed on KTR original report paper with hologram and when re-issued by KTR. The copy and the electronic file of the test report are only for reference.

Lee Jong Hun

Prepared by Lee Jong Hun

Tel : 02-2092-3824

Chang-Seok Jeong

Reviewed by Chang-Seok

Tel : 1577-0091(ARS ①→④)

2019.04.24

Korea Testing & Research Institute

President



QR Code for forgery